



DIR-815 Firmware Release Notes

Firmware: FW v1.03

Hardware: Rev.A1

Date: 2012/04/23

Problems Resolved:

1. Change band width default setting from HT20 to HT20/40 auto.
2. Fix wrong data rate issue.
3. Fix error message issue when enable/disable QoS engine. The setting can not be saved.
4. Enhance WPS-PIN security concern

Enhancements:

N/A.

Note:

N/A.

----- END -----